

ROAD CONSTRUCTION LABOR PERFORMANCE CONTROL USING PPC, PCR AND RNC DURING THE PANDEMIC

MG. ING. JORGE DE LA TORRE/BACH. ING. LUISA TABOADA/BACH. ING. POOL PICOY



Universidad Peruana de Ciencias Aplicadas





AGENDA

- 1. INTRODUCTION
- 2. METHOD
- 3. RESULTS
- 4. CONCLUSIONS



The **construction industry** has been critizicized and compared to other industries due to the reduced evolution of labor performance and the few tools established to control and improve it, which leads to wastes in the processes causing cost overruns and decreased productivity (Bølviken and Koskela, 2016).



Figure 1. Labour productivity of on-site construction (Figure 15 in Ahmad et al., 2020)



This defect is more frequent in road works due to its longitudinal nature; which leads to a large number of interferences that must be identified in a timely manner so as not to interrupt the work flow of resources, such as work force.



Figure 2. Road construction site



Within the context of the pandemic, the low performance of labor has been strengthened, due to the nature of the execution of its activities involving of numerous specialized work force teams working together and to the increase in working hours spent on non-contributory time (TNC).



Figure 3. Workmen within the context of the pandemic



Due to the problem of labor performance control in the context of a pandemic and the higher incidence of variability in road projects, this study aims to validate the use of PPC, PCR and RNC indicators as a mechanism labor for monitoring in road performance construction within the new normal.



Figure 4. Case study project



2. METHOD

Figure 5 represents the methodology used for the control of the labor performance of a road project within the context of the **new** normal using as a mechanism the PPC and PCR indicators and **RNC** for decision making oriented to continuous improvement.



Figure 5. Flowchart of Research Process



The survey was conducted among 40 professionals from 16 construction companies specializing in road projects during the new normal.

Survey results provided a situational overview of road works and guided the PPC and PCR indicators towards a controlled labor performance within the context of the new normal.



Figure 6. Factor of variability of the labor performance



22% of the professionals
rated Waiting or
Downtime as the waste
with the greatest impact
on labor performance.



Figure 7. Waste with the greatest impact on labor performance



The average Productive Time (TP), i.e., that which the time that workers add direct value to production of executed activities., represents 50.45% of the activities performed at the construction site.



Figure 8. Distribution of types of work times in road projects in the context of new normality



Regarding the <u>causes and consequences</u> of variability provided by road project specialists, they coincide in mentioning <u>causes</u> attributed to **external variability factors**. And on the the <u>consequences</u>, these coincide in waiting, delays, low productivity and labor performance rates, cost overruns, and missed deadlines.



Climate change not allow to asphalt or pur pavements



Underground interference in urban areas conduce to Halt of work due to new activities which require resolution



Incompatibility between technical file and field reality

Not having a complete report of interferences



2.2 IDENTIFICATION OF ITEMS WITH THE GREATEST INCIDENCE

N°	Item description	% impact on budget
1	Rigid Pavement	34.76%
2	Granular Sub-base H=20 cm	5.66%
3	Concrete Sidewalks	4.40%
4	Pavement painting	2.99%
5	Asphalt Contraction Joint Sealing	1.50 %
6	Excavation to subgrade in Loose Material	1.20%
7	Demolition of Flexible Pavement	1.18%

Table 1. Control items



2.3 WEEKLY PLANNING MEETING

Weekly planning meeting agenda																																									
	Week 2																																								
	Lookahead 2 @ 4																																								
Week 1							T	Week 2				Week 3				Week 4					Week 5						Week 6														
м	т	w	т	F	S	S	Ν	1 T	w	Т	F	S	S	м	т	w	т	F	S	S	м	Т	w	т	F	S	S	м	Т	w	Т	F	S	S	м	Т	W	Т	F	S	S
						Ex	e <mark>cu</mark>	ited V	Veek	k Rev	/iew	(We	eek 1))																											
							С	ompli	ance	e of a	activ	ities	5																												
V	/EEI	K 1	RE	VIE	W		С	alcula	ite P	РС																															
							D	eterm	nine f	RNC																		l v	VEE	К 1	PL	AN									
							С	orrect	tive a	actic	ons f	or R	NC																												
							С	alcula	ite P	CR																															
							Labor performance curves																																		
							С	orrect	tive a	actic	ons f	or de	elays	in c	ritica	al act	activitie										Į														
Immediate Post Week Planning ((We	ek 2)																															
							R	eview	of L	.ook	ahea	ad 2	2@4	rest	ricti	ons																									
							D	eterm	nine e	exec	utak	ole ta	asks (rele	asec	lcon	stra	ints)																							
							Define weekly work plan 2						n 2															I.v	VEE	К 2	PL	AN									
							Submit Lookahead 3 @ 5																																		
							С	onstra	aints	ana	alysis	s in a	accor	dano	ce to	the	Loo	kah	ead	3@	5																				
																										-	J														

PPC: Percentage of Plan completed

RNC: Reasons for Non Compliance

PCR: Percentage of Constraint Removal

Figure 9. Weekly Planning Meeting Agenda



2.3 LABOR PERFORMANCE CURVES

This graph identifies whether the labor resource meets the expected performance (input/output), according to the budget, because if the accumulated performance is higher than the budgeted performance, more manhours (input) are being used than **expected**, which translates into cost overruns.

			CONSORCIO VIAS DEL ESTE													
CONTRACTUAL ITEM:	Pavement pair	nting (m)				SUPPLIER:										
Date:	10-oct-20							PHASE:	100							
ltem	Unit	STRETCH	SIDE	INITIAL PROG.	FINAL PROG.	WIDTH	LENGTH	THICKNESS	QUANTITY	OBSERVATIONS						
Pavement painting (m)	m	I	LEFT	1+751	1+879		128	128 128.0								
						ſ	то	TAL M	128.00							
										,						
		Quantit	y	HOU	irs											
							REFERENCE PHOTO:									
						121 62		Marse F.								
SOIL COMPACTOR						10	the second second		1							
CISTERNE						190	A Content									
						0		LINKI								
MATERIALS		Unit		Quar	tity				and							
						- f		JAN THE STATE	and a second							
						11-1-10		2	and the							
						the second		The second second	Sector Sector	All shares and a state of the s						
						attended of	Contraction dan 14									
						and the	and the stand									
						1										
		Outerstit		llas			COMMENTS:									
		Quantit	y	Hou	115											
OPERATOR		10		۶ <i>۱</i>)											
OFFICIAL		1.0		8 (,)											
GENERAL LABORER		6.0		8.0												
CONTROLLER		,				1										

*NOTE: This form will be filled out for each item worked on and will be cumulative

Figure 9. Daily production report



3. RESULTS

At lower the PPC and PCR, the performance is higher, which translates into inefficient use of resources and cost overruns. This is due to the fact that, in the event of non-compliance with the release of constraints, the workflow is interrupted, which implies greater use of man-hours.



Figure 10. PPC and PCR chart



3. RESULTS

The improvement in **labor** performance begins in week 3, at which point the PPC and PCR tend to **rise**, which is explained by timely decisions and actions regarding labor and release of constraints.



Figure 11. Labor Performance Curves



3. RESULTS

According **RNCs** identified during the current health situation, the most frequent are the external ones with 42% since roadworks present factors specific to the type of project that can cause interruptions in the work flow throughout its development.



Figure 12. RNC Pareto Chart



3. RESULTS

	Workmen	Labor Performance (input/ou	Production speed (output/day)						
Item description	(a)	Budgeted	Start (b)	End (c)	$\frac{\text{Start}}{1}$ $\frac{1}{b/(a \times 8)}$	End $\frac{1}{c/(a \times 8)}$	Increase			
Rigid Pavement (m2)	18	0.16	0.17	0.16	848	905	7%			
Demolition of Flexible Pavement (m2)	6	0.19	0.02	0.01	2464	4657	89%			
Excavation to subgrade in Loose Material (m3)	3	0.09	0.08	0.07	305	350	15%			
Granular Sub-base H=20 cm (m2)	5	0.04	0.02	0.02	2340	2037	-13%			
Pavement painting (m)	8	0.64	0.62	0.20	104	320	208%			
Asphalt Contraction Joint Sealing (m)	14	1.13	0.09	0.07	1287	1512	17%			
Concrete Sidewalks (m2)	7	0.71	1.15	0.70	49	80	63%			

Table 2. Improvements in labor performance



4. CONCLUSIONS

It was found that the of labor monitoring performance of road construction projects through the PPC, PCR and RNC indicators generated positive impact on а improving labor performance in road projects developed during the new normal.

Specific external RNCs during the study period were heavy and light traffic problems in the work areas, as well as interference with residential access and domestic public services.



Better PPC and PCR were found to be directly related to a labor performance in line with the Budget





4. CONCLUSIONS

It was found that **low PPC** and PCR, translates into an **inefficient labor performance** which in turn leads to higher cost overruns for the road project



A 24% to 64% improvement in PPC resulted in up to 67.74% improvement in the work force performance of the pavement painting control item.



This study contributes to existing knowledge and practice, in the context of the pandemic, by validating the methodology for monitoring and optimizing the performance of the road construction work force using LPS indicators collecting RNCs and characteristic of the type of work and the health

crisis.



THANK YOU!

1 Magister Civil Engineer, Universidad Peruana de Ciencias Aplicadas, Lima, Peru, +51 975 355 566, <u>pccijdel@upc.edu.pe</u>, <u>orcid.org/0000-0003-3596-8196</u>

2 Bachelor of School of Civil Engineering, Universidad Peruana de Ciencias Aplicadas, Lima, Peru, +51 994 324 260, u201521217@upc.edu.pe, orcid.org/0000-0002-8413-5011

3 Bachelor of School of Civil Engineering, Universidad Peruana de Ciencias Aplicadas, Lima, Peru, +51 922 542 234, <u>u201316815@upc.edu.pe</u>, <u>orcid.org/0000-0003-2372-9083</u>

MG. ING. JORGE DE LA TORRE¹/BACH. ING. LUISA TABOADA²/BACH. ING. POOL PICOY³



